

Terrace Park of Five Towns #26

LOCATION:

ST. PETERSBURG, FLORIDA



IP RISK SERVICES, INC. 3559 Fairway Forest Drive, Suite 3559 Palm Harbor, Florida 34685

Email: IPRiskServices@aol.com

POWERED BY CORE LOGIC AND UNDERWRITTEN BY LLOYD'S OF LONDON









14.



IP

CEPE OF CONTENTS

1.	Introduction
2.	Hazard & Flood requirements
3.	Recapitulation Of Values
4.	Insurance exclusions
5.	Building Descriptions
6.	Value Explanations
7.	ISO Construction Classifications
8.	Core Logic Estimating Readouts
9.	Photographs
10.	Annual Update Services
11.	Reserve Study Services
12.	Building Code Services
13.	Staff and Qualifications

IP

Limiting Conditions



INSURANCE INSPECTION REPORT



PREPARED FOR THE FOLLOWING INSURANCE RISK: TERRACE PARK OF FIVE TOWNS #26

LOCATION: ST. PETERSBURG, FLORIDA

THIS INSURANCE INSPECTION REPORT WAS CREATED TO ASSIST INSURANCE UNDERWRITERS IN CORRECT IDENTIFICATION OF CONSTRUCTION COMPONENTS FOR INSURANCE RATING PURPOSES. THE REPORT IDENTIFIES THE COMPONENTS CONSTRUCTION OF THE RISK IN ORDER TO MEET CERTAIN REQUIREMENTS OF AN INSURANCE POLICY. THE REPORT ASSISTS IN AVOIDING CO-INSURANCE PENALTIES OF THE INSURANCE POLICIES. THIS REPORT IS IN ADHERENCE WITH STATE INSURANCE STATUTES AND FEDERAL FLOOD INSURANCE REQUIREMENTS.

THE REPORT IDENTIFIES AREAS SUCH AS THE ROOF, EXTERIOR WALLS, FOUNDATIONS, FRAME, FLOORS, CONVEYING SYSTEMS, KITCHENS, HVAC, ELECTRICAL, PLUMBING, FIRE SPRINKLERS AND OTHER CONSTRUCTIONCOMPONENTS VITAL TO THE INSURANCE RATING.

THIS REPORT IS NOT A REAL ESTATE APPRAISAL. THIS REPORT IS AN INSURANCE REPORT ONLY. THE CONCLUSIONS IN THIS REPORT UTILIZE ACCEPTABLE INSURANCE METHODS ONLY.

AN INSURANCE INSPECTION HAS BEEN MADE OF THE RISKS IN THIS REPORT.

UPDATE- October 18, 2024

Original Inspection- Craig Markowich

P/P Consultants:

CRAIG MARKOWICH, FL Lic CL520 KEN TAZZA, FL Lic WO31043 KAREN G. LEWANICK JONATHAN FIELDS CRAIG MARKOWICH KEN TAZZA KAREN G. LEWANICK JONATHAN FIELDS

I P Risk Services, Inc. 3559 Fairway Forest Drive, Suite 3559 Palm Harbor, Florida 34685

Email: IPRiskServices@aol.com
Core Logic Estimating System



***** ELOPIDA CONDOMINIUM LAWS DEOVIDE AN

****** FLORIDA CONDOMINIUM LAWS PROVIDE AN EXCLUSION OPTION ON CERTAIN ITEMS AS DESCRIBED BELOW:

A hazard insurance policy issued to an association must provide primary coverage for all condominium property as originally installed or replacements of like kind and quality in accordance with original plans and specifications, and all alterations or additions made to condominium or association property but **excluding** all personal property within a unit or limited common element; floor; wall and ceiling coverings; electrical fixtures; appliances; water heaters; water filters; built-in cabinets and countertops; and window treatments; including curtains; drapes; blinds; hardware; and similar window treatment components or replacements of any of the foregoing which are located within the boundaries of a unit and serve only one unit.

The foregoing is intended to establish the property or casualty insuring responsibilities of the association and those of the individual unit owner and do not serve to broaden or extend the perils of coverage afforded by any insurance contract provided to the individual unit owner.





INSURANCE RESPONSIBILITIES AS GOVERNED BY FLORIDA STATUTE 718

	Condominium Association Responsibility	Individual Unit Owner Responsibility
1. ROOF AND ROOF COVER Structural Framing and Roo	YES of Cover	NO
2. EXTERIOR WALLS Paint, stucco, insulation, st Concrete Block, Brick, etc.	YES auds,	NO
3. UNIT INTERIOR WALLS Party Walls, Unfinished dryg insulation, metal and wood	-	NO
4a. COMMON AREA Interior W Studs, Block and Drywall 4b. COMMON AREA Floor, Wa	YES	NO
and Ceiling Finishes	YES	NO
5. UNIT INTERIOR Floor, Walk	 l & Ceiling Finishes	
Paint, Carpet, tile, etc.	NO	YES
6. UNIT AND COMMON AREA		
-Structural Floors	YES	NO
-Structural Ceilings	YES	NO
-Structural Walls	YES	NO
7. Common Area Air Condition	ners <i>YES</i>	NO
8. Common Area Electrical	YES	NO
9. INTERIOR UNIT COMPONE	 NTS	
- Appliances	NO	YES
- Electrical Fixtures	NO	YES
- Air Conditioners	YES	NO
- Water Heaters	NO	YES
- Cabinets	NO	YES

^{****}The above information is intended to assist in determining the general responsibilities for both parties. IP makes no warranties as to individual Association legal interpretations.



MANDATORY FEDERAL FLOOD INSURANCE POLICY REQUIREMENTS

FEDERAL FLOOD REQUIREMENTS INCLUDE THE THE FOLLOWING ITEMS FOR RESIDENTIAL CONDOMINIUM UNITS:

- All Foundations including below ground
- All Piping including below ground
- All Excavation and site preparation work
- All Structural floors, walls, ceilings and roof
- All Electrical Wiring and Plumbing
- All Interior Floor Wall & Ceiling Finishes
- All appliances, air conditioners, water heaters Electrical fixtures and built-in cabinets.

ALL CONDOMINIUMS ARE MANDATED TO ADHERE TO THE FEDERAL FLOOD REQUIREMENT VALUATIONS.

IP REP	PORTS REFLEC	T THESE GUIDELINES	5.

INSURANCE RESPONSIBILITIES AS GOVERNED BY NATIONAL FLOOD INSURANCE PROGRAM-FEMA

	Condominium Association Responsibility	Individual Unit Owner Responsibility
1. ROOF AND ROOF COVER Structural Framing and Roof	YES Cover	NO
2. EXTERIOR WALLS Paint, stucco, insulation, stu Concrete Block, Brick, etc.	YES ds,	NO
3. UNIT INTERIOR WALLS Party Walls, Unfinished drywinsulation, metal and wood st	•	NO
4a. COMMON AREA Interior Wa Studs, Block and Drywall 4b. COMMON AREA Floor, Wall	YES	NO
and Ceiling Finishes	, YES	NO
5. UNIT INTERIOR <i>Floor, Wall Paint, Carpet, tile, etc.</i>	& Ceiling Finishe YES	s NO
6. UNIT AND COMMON AREA		
-Structural Floors	YES	NO
-Structural Ceilings	YES	NO
-Structural Walls	YES	NO
7. Common Area Air Condition	ers <i>YES</i>	NO
8. Common Area Electrical	YES	NO
9. INTERIOR UNIT COMPONEN	TS	
- Appliances	YES	NO
 Electrical Fixtures 	YES	NO
- Air Conditioners	YES	NO
- Water Heaters	YES	NO
- Cabinets	YES	NO

^{****}The above information is intended to assist in determining the general responsibilities for both parties. IP makes no warranties as to individual Association legal interpretations.







HAZARD INSURANCE REQUIREMENTS

10/2024 TERRACE PARK OF FIVE TOWNS- NUMBER 26

The below analysis is in adherence with Florida Insurance Statute 718 and exclude certain items as explained in the report.

RISK	INSURABLE REPRODUCTION	LESS FOUNDATION EXCLUSIONS	INSURABLE REPRODUCTION
ASTOR	2,150,488	95,960	2,054,628
BELMONT	1,958,606	85,117	1,873,489
CAMBRIDG	E 1,958,606	85,117	1,873,489
Carports	169,000		169,000
Grand Tota	al 6,236,70	0 266,194	5,970,506



RESERVES, INC.



******INSURANCE RISK FLOOD REQUIREMENTS

The below tabulation analysis can be utilized for any Federal Flood insurance requirements. As mandated, this analysis includes all interior floor, wall and ceiling finishes. The analysis also includes appliances, cabinets, electrical fixtures, mechanical equipment and foundations below ground. Common area Structures are tabulated on a depreciated basis according to insurance Flood requirements. 10/2024

Terrace Park of Five Towns- No. 26 Condominium St. Petersburg, Florida 33709

ASTOR 2,714,052 8108 & 8110 Terrace Garden North

2,538,323 8140 Terrace Garden Drive North BELMONT

CAMBRIDGE 2,538,323 8162 Terrace Garden Drive North

GRAND TOTAL

7,790,698

IP







INSURANCE EXCLUSIONS

CERTAIN ITEMS ARE EITHER NOT INSURED, OR ARE SPECIFICALLY EXCLUDED FROM COVERAGE, DEPENDING ON THE PARTICULAR TERMS OF AN INSURANCE POLICY.

FOUNDATIONS <u>BELOW</u> GROUND AND PIPING <u>BELOW</u> GROUND ARE NORMALLY EXCLUDED FOR INSURANCE PURPOSES.

THE EXCLUSION FIGURES IN THE HAZARD

RECAPITULATION PAGE ARE THE CALCULATED

PERCENTAGES OF FOUNDATIONS AND PIPING

BELOW GROUND.

POWERED BY CORE LOGIC AND UNDERWRITTEN BY LLOYD'S OF LONDON



NSURANGE CONSTRUCTION DESCRIPTIONS

RISK NAME: TERRACE PARK #26 CONDOMINIUM.

RISK LOCATION: ST. PETERSBURG, FLORIDA.

RISK USE: THREE RESIDENTIAL BUILDINGS.

GROSS FLOOR AREA: APPROXIMATE:

ASTOR 10-UNIT = 17,200 SQUARE FEET

BELMONT 8-UNIT = 15,900 SQUARE FEET

CAMBRIDGE 8-UNIT = 15,900 SQUARE FEET

STORIES: TWO TOTAL STORIES.

FOUNDATION: POURED CONCRETE FOOTINGS.

FRAME: BEARING WALL CONSTRUCTION.

EXTERIOR WALLS: MASONRY BLOCK, STUCCO, PAINT AND POURED CONCRETE.

FLOORS: CONCRETE.

ROOF: PITCHED WOOD RAFTERS, WOOD DECKING WITH WITH TILE COVER.

CONVEYING SYSTEMS: STAIRWELLS.

KITCHENS: Each unit contains one residential style kitchen per unit with appliances such as Refrigerator, Stove, Sink, Dishwasher and Cabinets. AS PER FLORIDA CONDOMINIUM LAW, THESE ITEMS ARE NOT INCLUDED IN THE HAZARD SECTION OF THIS REPORT. CABINETS AND SHELVING ARE ALSO NOT INCLUDED IN THIS REPORT.

FLOORS: INCLUDED AT COMMON AREAS ONLY; ALL INTERIOR FLOOR COVERINGS ARE INCLUDED IN THE FLOOD SECTION.

WALLS: INCLUDED AT COMMON AREAS ONLY; ALL INTERIOR WALL COVERINGS ARE INCLUDED IN THE FLOOD SECTION.

CEILINGS: INCLUDED AT COMMON AREAS ONLY; ALL INTERIOR CEILING COVERINGS ARE INCLUDED IN THE FLOOD SECTION.

PARTITIONS: PRIMARILY STUD, DRYWALL AND CONCRETE BLOCK.

HVAC: INDIVIDUAL AC UNITS PER UNIT.

ELECTRICAL: AVERAGE ELECTRICAL SYSTEM; INTERIOR LIGHT FIXTURES ARE NOT INCLUDED IN THIS REPORT AS PER FLORIDA CONDOMINIUM LAWS.

PLUMBING: FULL BATHROOMS PER UNIT.

SPRINKLERS: N/A.



SPECIALTIES:

1) **Carports**- The carports are of standard corrugated metal construction.

ASTOR

5-Stall = \$32,500

5-Stall = \$32,500

Belmont

8-Stall = \$52,000

Cambridge

8-Stall = \$52,000

Carport Total = \$169,000

I P Risk Services, Inc.

IP Risk Services is proud to offer our clients three of arguably the most **sophisticated** Insurance Rating Estimating Systems and Experts available in the World today.

- Core Logic Company
- RS Means Building Construction Cost Data
- IP Risk Services Expert/Licensed Staff

IP Risk Services has been granted a License by the Core Logic Company to utilize and offer the **Commercial Building Insight/Rating** Estimating System.

This system utilizes a "component by component" study of Material & Labor costs. Each component is judged individually such as foundations, exterior walls, under air etc. This type of approach is many times more accurate than the often used inexpensive General Book system that utilizes General local multipliers.

CBI is an inductive estimating product which analyzes user input to automatically select **component** costs for walls, doors, windows, roof cove and the like. When grouped together, multiple assemblies become systems of the building, such as the Exterior Wall, Roof, Partition, HVAC or similar. When the building systems are added together, inclusive of other "soft costs" of construction like **Overhead & Profit** (**OH & P**), fees and permits, architects fees, and similar, respective costs are used to develop a profile for a particular type of Building.

CBI continuously monitors advances in building construction methods to ensure component parts of our estimating system reflect current construction techniques.

When new techniques and specifications become main-stream practice, it can affect the component selections of the system and ultimate amounts produced.

The **CBI** system **Updates** all **Material & Labor** changes every three months.

CBI continually researches labor, material and equipment costs ("hard costs" of construction) plus mark-ups, taxes, insurance, fees and permits and other fringes delivered for reconstruction work for the insurance industry in the United States and Canada. Over 50 research professionals, the largest force in the industry, monitor data from nearly 3,000 areas in the United States.

ΙP

IP Risk Services, Inc.



The following information and definitions have been compiled by the <u>RSMeans</u> company.

The <u>RSMeans</u> company is recognized as a top leader of providing insurance Replacement cost information to the insurance industry for many years.

Since 1942, RSMeans has been actively engaged in construction cost publishing and consulting throughout North America.

OVERHEAD & PROFIT

General contractor overhead includes indirect costs such as permits, workers compensation, insurances, supervision and bonding fees.

Overhead COSTS WILL VARY with the size of the project, the contractor's operating procedures and LOCATION.

PROFIT WILL "VARY" WITH ECONOMIC ACTIVITY AND LOCAL CONDITIONS.

In ALL situations, the inspector should give consideration to possible adjustment of the factors used in developing the Commercial/Residential models.

ARCHITECTURAL FEES

Typical Architectural Fees may "VARY" depending upon the degree of design difficulty and ECONOMIC CONDITIONS in any particular area.

Various portions of the SAME project requiring different percentages should be adjusted proportionately.

***** RSMeans Company



IP NOTE

The above guidelines have been the basis and foundation of providing ACCURATE insurance estimates in the insurance industry for many years.

The above guidelines are common sense. They prove that there is NOT any type of "Standard" percentages that must be utilized when compiling an accurate insurance estimate.

Professional and ethical insurance estimating companies must take the time/effort needed to compile the correct replacement costs of a particular location.

This time/effort procedure always reveals different replacement costs percentages based on economic conditions and location.

Professional insurance estimating companies should never let any person or any type of "entity" dictate to them the percentages that must be utilized in the production of an accurate insurance estimate.

Professional insurance estimating companies must maintain the identity as an "unbiased disinterested third party opinion" and not yield to pressure from any other entity.

Parties and Entities (such as Insurance Companies) that have a **vested** interest are not; nor have they ever been considered an unbiased source of true replacement costs since they have an interest in the outcome of an insurance estimate.

This fact has been proven many times in the legal system.

Property Owners should always seek an insurance replacement cost estimate from an unbiased disinterested legitimate third party professional company.

IP Risk Services has always abided by the industry guidelines that have been eloquently stated by the RSMeans Company.

IP Risk Services has always maintained the highest integrity as an unbiased disinterested third party opinion.

IP Risk Services does **not** and will never have any type of **vested** interest in the properties that we provide insurance estimate opinions.



I P Risk Services, Inc.



IP Risk Services also utilizes the inductive method of cost compilation to help **confirm** our findings. In this method, wage rates, material prices and other base costs are combined into unit-in-place costs, which are then grouped into component-in-place costs.

This check system utilizes time-location multipliers to adjust building base costs to **local costs** and the current **date** of the study.

Time-location multipliers and **local economic conditions** are monitored continuously by our "on the ground in the market" **IP Personnel**. This monitoring staff may consist of a Licensed General Building Contractor, Licensed All Lines Commercial Property Adjuster, Licensed Certified Commercial Appraiser and Licensed Insurance Agent.

FLORIDA LOCATION FACTORS

1. Jacksonville	.78
2. Daytona Beach	.80
3. Tallahassee	.72
4. Panama City	.67
5. Pensacola	.75
6. Gainseville	.77
7. Orlando	.85
8. Melbourne	.84
9. Miami	.80
10. Fort Lauderdale	.86
11. West Palm Beach	.83
12. Tampa	.79
13. St. Petersburg	.75
14. Lakeland	.80
15. Ft. Myers	.83
16. Sanibel	.95
17. Sarasota	.92
18. Palm Beach	.93

The above multipliers showcase the general cost differences for replacement factors based on **location**. **Local economic** conditions must also be considered for the most accurate replacement estimates in a particular area.

Powered by Core Logic and Underwritten by Lloyd's of London

I P Risk Services, Inc.



FR= FIRE RESISTIVE (ISO 6)

Building where the exterior walls and floors, roof are constructed of masonry or fire resistive materials having a fire resistance rating of not less than two hours.

FR= MODIFIED FIRE RESISTIVE (ISO 5)

Building where the exterior walls and the floors, roof are constructed of masonry or fire resistive materials with a fire resistance rating of one hour or more but less than two hours.

JM= JOISTED MASONRY (ISO 2)

Building where the exterior walls are constructed of masonry materials such as brick, adobe, concrete, gypsum block, concrete block, stone, tile or similar materials and where the floors and roof are combustible.

F = FRAME (ISO 1)

Building where the exterior walls are wood or other combustible materials, including construction where combustible materials are combined with other materials such as brick, stone veneer, wood and stucco on wood framing.

MNC = MASONRY NONCOMBUSTIBLE (ISO 4)

Building where the exterior walls are constructed of masonry materials with the floors and roof of metal or other noncombustible materials

NC = NONCOMBUSTIBLE (ISO 3)

Building where the exterior walls, floors and the roof are constructed of, and supported by, metal, asbestos, gypsum or other noncombustible materials.

SUPERIOR MASONRY NONCOMBUSTIBLE (ISO 9)

Building where the entire roof is constructed of two inches of masonry on steel supports or when the entire roof is constructed of 22 gauge metal on steel supports or when the entire roof has a wind uplift classification of 90 or equivalent.

Powered by Core Logic and Underwritten by Lloyd's of London







OUR CONSULTING STAFF INCLUDES A COMBINED 205+ YEARS OF INSURANCE AND CONSTRUCTION EXPERIENCE:

- 1. CRAIG MARKOWICH
- 2. KEN TAZZA
- 3. JONATHAN FIELDS CONSTRUCTION
- **4. KAREN LEWANICK**
- 5. Estimating System Licensed thru Core Logic
- 6. Insurance underwritten by Lloyd's of London



IP Risk Services, Inc. P: (404) 317- 7140

3559 Fairway Forest Drive, Suite 3559

Palm Harbor, FL 34685 Email: IPRiskServices@aol.com







Typical Belmont & Cambridge
Hazard Detailed

10/18/2024

VALUATION

Value Basis:

Valuation Number: ESTIMATE-0002088

Effective Date: 10/18/2024

Reconstruction Expiration Date: 10/18/2025

Estimate Expiration Date: 10/30/2025

Cost as of: 09/2024

Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 0000000 - #26

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium, w/o Interior Story Height: 9 ft.

Finishes

Construction Type: 100% Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 15,900 sq.ft. Irregular None

Adjustment:

Construction Quality: 2.0 - 2.0 - Average

Year Built:

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Typical Belmont & Cambridge Hazard Detailed

Policy Number: ESTIMATE-0002088 10/18/2024

Overhead and Profit:	20% is included			
SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation				\$2,385
Foundations			\$60,944	\$48,966
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$434,534	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$291,376	
Material	100% Tile, Clay			
Pitch				
Interior			\$480,279	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		2,271 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$423,367	\$33,767
Heating	90% Heat Pump			
Cooling	90% Heat Pump			
Fire Protection		0% Sprinkler System		
		0% Manual Fire Alarm System		
		0% Automatic Fire Alarm System		
Plumbing	80 Total Fixtures			
Electrical		100% Average Quality		

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Typical Belmont & Cambridge

Hazard Detailed

Policy Number: ESTIMATE-0002088 10/18/2024

SUMMARY OF COSTS	User Provided	System Provide	ed Rec	construction	Exclusion
Elevators		0 Passenger			
		0 Freight			
Built-ins				\$182,989	
TOTAL RC Section 1				\$1,873,489	\$85,117
TOTAL RC BUILDING 000000	0 #26			\$1,873,489	\$85,117
		Reconstruction	Sq.Ft.		
LOCATION TOTAL, Location 1		\$1,873,489	15,900		
		Reconstruction	Sq.Ft.		
VALUATION GRAND TOTAL		\$1,873,489	15,900		

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Typical Belmont & Cambridge Hazard Detailed SUMMARY REPORT

Policy Number: ESTIMATE-0002088 10/18/2024

VALUATION

Valuation Number: ESTIMATE-0002088 Effective Date: 10/18/2024 Value Basis: Reconstruction **Expiration Date:** 10/18/2025

Estimate Expiration Date: 10/30/2025 Cost as of: 09/2024 Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

BUILDING	0000000: SI	JPERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section	1 100%	Condominium, w/o Interior Finishes	\$1,873,489	15,900	\$118	
Section	Totals		Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section	1 100%	Condominium, w/o Interior Finishes	\$1,873,489	15,900	\$118	
BUILDING	TOTAL, Bui	lding 0000000	\$1,873,489	15,900	\$118	
BUILDING	INSURANC	E SUMMARY				
Total Insure	d Amount		\$0			
Percent of I	nsurance to	Value	0%			
100% Co-in	surance Red	quirement	\$1,873,489			\$1,873,489
-100% Varia	ance		(\$1,873,489)			
			Reconstruction	Sq.Ft.		
OCATION TO	TAL, Locat	ion 1	\$1,873,489	15,900		
			Reconstruction	Sq.Ft.		
ALUATION (RAND TOT	AL	\$1,873,489	15,900		

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Typical Belmont & Cambridge
Hazard Detailed

Policy Number: ESTIMATE-0002088 10/18/2024

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building
Hazard Detailed

10/18/2024

VALUATION

Value Basis:

Valuation Number: ESTIMATE-0002088

Effective Date: 10/18/2024

Reconstruction Expiration Date: 10/18/2025

Estimate Expiration Date: 10/30/2025

Cost as of: 09/2024

Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 0000000 - #26

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium, w/o Interior Story Height: 9 ft.

Finishes

Construction Type: 100% Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 17,200 sq.ft. Irregular None

Adjustment:

Construction Quality: 2.0 - 2.0 - Average

Year Built:

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building Hazard Detailed

Policy Number: ESTIMATE-0002088 10/18/2024

Overhead and Profit:	20% is included			
SUMMARY OF COSTS	User Provided	System Provided	Reconstruction	Exclusion
SUPERSTRUCTURE				
Site Preparation				\$2,580
Foundations			\$65,927	\$51,172
Foundation Wall				
Interior Foundations				
Slab On Ground				
Exterior			\$459,764	
Framing				
Exterior Wall		25% Wall Openings		
Exterior Wall	100% Stucco on Masonry			
Structural Floor				
Roof			\$312,833	
Material	100% Tile, Clay			
Pitch				
Interior			\$518,511	
Floor Finish				
Ceiling Finish		100% Drywall		
Partitions				
Length		2,457 ft.		
Structure		100% Studs, Girts, etc.		
Finish		100% Drywall		
Mechanicals			\$499,642	\$42,208
Heating	90% Heat Pump			
Cooling	90% Heat Pump			
Fire Protection		0% Sprinkler System		
		0% Manual Fire Alarm System		
		0% Automatic Fire Alarm System		
Plumbing	100 Total Fixtures			
Electrical		100% Average Quality		

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building
Hazard Detailed

Policy Number: ESTIMATE-0002088 10/18/2024

SUMMARY OF COSTS	User Provided	System Provide	d Rec	construction	Exclusion
Elevators		0 Passenger			
		0 Freight			
Built-ins				\$197,951	
TOTAL RC Section 1				\$2,054,628	\$95,960
TOTAL RC BUILDING 000000	0 #26			\$2,054,628	\$95,960
		Reconstruction	Sq.Ft.		
LOCATION TOTAL, Location 1		\$2,054,628	17,200		
		Reconstruction	Sq.Ft.		
VALUATION GRAND TOTAL		\$2,054,628	17,200		

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building
Hazard Detailed
SUMMARY REPORT

Policy Number: ESTIMATE-0002088 10/18/2024

VALUATION

Valuation Number:ESTIMATE-0002088Effective Date:10/18/2024Value Basis:ReconstructionExpiration Date:10/18/2025

Estimate Expiration Date: 10/30/2025

Cost as of: 09/2024

Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

В	JILDING 000	0000: SU	PERSTRUCTURE	Reconstruction	Sq.Ft.	
	Section 1	100%	Condominium, w/o Interior Finishes	\$2,054,628	17,200	
	Section Tot	als		Reconstruction	Sq.Ft.	
	Section 1	100%	Condominium, w/o Interior Finishes	\$2,054,628	17,200	
В	JILDING TOT	AL, Buil	ding 0000000	\$2,054,628	17,200	
В	JILDING INS	URANCE	SUMMARY			
To	otal Insured A	mount		\$0		
Pe	ercent of Insur	rance to \	/alue	0%		
10	0% Co-insura	ance Req	uirement	\$2,054,628		\$2,054,628
-1	00% Variance)		(\$2,054,628)		
				Reconstruction	Sq.Ft.	
OC/	ATION TOTA	L, Locati	on 1	\$2,054,628	17,200	
				Reconstruction	Sq.Ft.	
/AL	JATION GRA	ND TOTA	AL.	\$2,054,628	17,200	

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building Hazard Detailed

Policy Number: ESTIMATE-0002088 10/18/2024

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

FLOOD VALUATION



ESTIMATE READOUTS

POWERED BY CORE LOGIC AND UNDERWRITTEN BY LLOYD'S OF LONDON



Valuation Standard Report

Typical Belmont & Cambridge Flood Valuation

10/18/2024

VALUATION

Valuation Number:

ESTIMATE-0002088

Effective Date: 10/18/2024

Value Basis: Reconstruction Expiration Date: 10/18/2025

Estimate Expiration Date: 10/30/2025

Cost as of: 09/2024

Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 0000000 - #26

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium Story Height: 9 ft.

Construction Type: 100% Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 15,900 sq.ft. Irregular None

Adjustment:

Construction Quality: 2.0 - 2.0 - Average

Year Built:

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Valuation Standard Report

Typical Belmont & Cambridge Flood Valuation

Policy Number: ESTIMATE-0002088 10/18/2024

Overhead and Profit:	20% is included	
SUMMARY OF COSTS		Reconstruction Exclusion
SUPERSTRUCTURE		
Site Preparation		\$2,323
Foundations		\$107,067
Foundation Wall, Interior	Foundations, Slab On Ground	
Exterior		\$707,136
Framing, Exterior Wall, E	xterior Wall, Structural Floor, Roof	
Interior		\$626,148
Floor Finish, Ceiling Finis	h, Partitions	
Mechanicals		\$889,365
Heating, Cooling, Fire Pro	otection, Plumbing, Electrical, Elevators	
Built-ins		\$206,282
TOTAL RC Section 1		\$2,538,323
OTAL RC BUILDING 000000	00 #26	\$2,538,323
	Reconstruction	Sq.Ft.
ATION TOTAL, Location 1	\$2,538,323	15,900
	Reconstruction	Sq.Ft.
JATION GRAND TOTAL	\$2,538,323	15,900

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Typical Belmont & Cambridge Flood Valuation SUMMARY REPORT

Policy Number: ESTIMATE-0002088 10/18/2024

VALUATION

Valuation Number:ESTIMATE-0002088Effective Date:10/18/2024Value Basis:ReconstructionExpiration Date:10/18/2025

Estimate Expiration Date: 10/30/2025

Cost as of: 09/2024

Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

BUILDING 0000000: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	
Section 1 100% Condominium	\$2,538,323	15,900	
Section Totals	Reconstruction	Sq.Ft.	
Section 1 100% Condominium	\$2,538,323	15,900	
BUILDING TOTAL, Building 0000000	\$2,538,323	15,900	
BUILDING INSURANCE SUMMARY	,		
Total Insured Amount	\$0		
Percent of Insurance to Value	0%		
100% Co-insurance Requirement	\$2,538,323		\$2,538,323
-100% Variance	(\$2,538,323)		
	Reconstruction	Sq.Ft.	
LOCATION TOTAL, Location 1	\$2,538,323	15,900	
	Reconstruction	Sq.Ft.	
VALUATION GRAND TOTAL	\$2,538,323	15,900	

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building Flood Valuation

10/18/2024

VALUATION

Valuation Number: ESTIMATE-0002088

Effective Date: 10/18/2024

Value Basis: Reconstruction Expiration Date: 10/18/2025

Estimate Expiration Date: 10/30/2025

Cost as of: 09/2024

Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 0000000 - #26

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium Story Height: 9 ft.

Construction Type: 100% Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 17,200 sq.ft. Irregular None

Adjustment:

Construction Quality: 2.0 - 2.0 - Average

Year Built:

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building Flood Valuation

Policy Number: ESTIMATE-0002088 10/18/2024

Overhead and Profit:	20% is included	
SUMMARY OF COSTS		Reconstruction Exclusion
SUPERSTRUCTURE		
Site Preparation		\$2,513
Foundations		\$114,070
Foundation Wall, Interior F	oundations, Slab On Ground	
Exterior		\$752,616
Framing, Exterior Wall, Ex	terior Wall, Structural Floor, Roof	
Interior		\$676,187
Floor Finish, Ceiling Finish	n, Partitions	
Mechanicals		\$945,518
Heating, Cooling, Fire Pro	tection, Plumbing, Electrical, Elevators	
Built-ins		\$223,148
TOTAL RC Section 1		\$2,714,052
TOTAL RC BUILDING 000000	0 #26	\$2,714,052
	Reconstruction	Sq.Ft.
CATION TOTAL, Location 1	\$2,714,052	17,200
	Reconstruction	Sq.Ft.
LUATION GRAND TOTAL	\$2,714,052	17,200

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Astor Building
Flood Valuation
SUMMARY REPORT

Policy Number: ESTIMATE-0002088 10/18/2024

VALUATION

Valuation Number: ESTIMATE-0002088 Effective Date: 10/18/2024

Value Basis: Reconstruction Expiration Date: 10/18/2025

Estimate Expiration Date: 10/30/2025

Cost as of: 09/2024

Valuation Modified Date: 10/18/2024

BUSINESS

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

LOCATION 1 - Terrace Park of Five Towns #26

Terrace Park of Five Towns #26

Terrace Garden Drive North

SAINT PETERSBURG, FL 33709 USA

BUILDING 0000000: SUPERSTRUCTURE	Reconstruction	Sq.Ft.	
Section 1 100% Condominium	\$2,714,052	17,200	
Section Totals	Reconstruction	Sq.Ft.	
Section 1 100% Condominium	\$2,714,052	17,200	
BUILDING TOTAL, Building 0000000	\$2,714,052	17,200	
BUILDING INSURANCE SUMMARY			
Total Insured Amount	\$0		
Percent of Insurance to Value	0%		
100% Co-insurance Requirement	\$2,714,052		\$2,714,052
-100% Variance	(\$2,714,052)		
	Reconstruction	Sq.Ft.	
LOCATION TOTAL, Location 1	\$2,714,052	17,200	
	Reconstruction	Sq.Ft.	
VALUATION GRAND TOTAL	\$2,714,052	17,200	
			

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.

PHOTOGRAPHS



Terrace Park Of Five Towns Number 26 Condominium

- ASTOR BUILDING
- BELMONT BUILDING
- CAMBRIDGE BUILDING





































































INSURABLE CONSTRUCTION AND LAWS GOVERNING INSURABLE RESPONSIBILITY CONTINUE TO CHANGE.

WE CAN UPDATE THIS INSURANCE REPORT
WITHOUT GOING TO THE ADDITIONAL EXPENSE OF
ANOTHER INSPECTION. THIS SERVICE WILL KEEP
THE ASSOCIATION CURRENT ON ALL CHANGES.

WE MAY HAVE TO REINSPECT THE RISK FOR ANY MAJOR CHANGES TO THE INSURABLE ITEMS. NORMAL MAINTENANCE WOULD *NOT* REQUIRE ANOTHER INSPECTION.

WE ALSO HAVE AN AUTOMATIC ANNUAL UPDATE SERVICE. IP WILL UPDATE THE REPORT AUTOMATICALLY EVERY YEAR WITHOUT ANY EFFORT FROM THE OWNERS.



IPRISKSERVICES@AOL.COM

P: (404) 317-7140

IP



RESERVE STUDIES



IP RISK SERVICES ALSO OFFERS COMPLETE RESERVE STUDY REPORTS.

WE WERE THE FIRST MAJOR COMPANY TO OFFER RESERVE STUDY REPORTS FOR CONDOMINIUM ASSOCIATIONS.

MANY HAVE TRIED TO COPY OUR FORMAT BUT OUR EXPERTISE AND *PIONEER* REPORTS CANNOT BE DUPLICATED.

WE ARE KNOWN TO HAVE THE MOST "USER FRIENDLY" RESERVE STUDY REPORTS IN THE INDUSTRY AS WE DO NOT INSERT WORTHLESS FILLERS SUCH AS GRAPHS AND CHARTS INTO OUR REPORTS. We just report the FACTS and real COSTS.

WE CAN OFFER YOUR ASSOCIATION A SUBSTANTIAL DISCOUNT BASED ON OUR RECENT APPRAISAL REPORT. JUST REQUEST YOUR DISCOUNT.

IPRISKSERVICES@AOL.COM

P: (404) 317-7140

IP



New Building Codes



One of the most overlooked insurance situations in a serious loss involves **new building codes and local ordinances** that may have been updated, changed or even added since the original construction of a building.

A further insurance situation involves **debris removal** after a serious loss. Debris from a loss must be removed before re-construction can begin.

New building codes and debris removal can sometimes be very costly and often overlooked by all parties involved in an insurance loss.

It is in the best interest of the insured to have an **estimate** for these two hazards even if the policy covers this cost.

IP **EXCLUSIVELY** offers a "**Theoretical Value Estimate**" for current building codes and debris removal.

Our 31 years of experience in the Florida market has enabled us to develop an exclusive formula for estimating these two important costs.

Just request us to provide you with this exclusive service.

IP

IP Risk Services carries complete Professional Appraisal Liability Insurance Underwritten thru:

LLOYD'S

LLOYD'S OF LONDON

THE ULTIMATE PROTECTION FOR ASSOCIATIONS AND BOARD MEMBERS

Our Commitment to Customer Excellence IP



IP



"EXPERIENCE MAKES A DIFFERENCE"

ALL OF OUR PAST REPORTS HAVE BEEN PRODUCED AND REVIEWED BY A MINIMUM OF AT LEAST ONE OF THE FOLLOWING LICENSED PROFESSIONALS:

- 1. Florida State Certified General Real Estate Appraiser
- 2. Florida All Lines Insurance Adjuster
- 3. Florida Licensed General Building Contractor
- 4. Florida Licensed Insurance Agent
- 5. Estimating System Licensed thru Core Logic, Inc.
- 6. Insurance Underwritten by Lloyd's of London.

IP Risk Services has been providing Insurance Services to ALL of Florida for over 32 years strong.

Our impeccable reputation and acceptance by ALL Insurance Companies and ALL Parties is well known from the Florida Panhandle to the Florida Keys.

Our longevity exhibits our expertise and commitment.



IPRISKSERVICES@AOL.COM

404-317-7140







CITIZEN PROPERTY INSURANCE CORPORATION

Minimum Requirements for Non-Licensed Commercial Residential Inspections/Valuation

In accordance with Citizens Property Insurance Corporation Agent Technical Bulletin 006-20 dated July 14, 2010, the following information is required:

CERTIFICATION

Name of the firm of key personnel completing the inspection/valuation: IP RISK SERVICES, INC. and Craig Markowich

I, Craig Markowich certify that I, or the entity listed above have/has at least three (3) years experience in the field of commercial property inspections, commercial risk assessment, and commercial property replacement cost evaluation.

Date: October 18, 2024

Craiq Markavich

Craig Markowich

Florida License, CL520

PROPERTY

Five Towns- No. 26
Terrace Garden Drive North
St. Petersburg, Florida

VALUATION REQUIREMENTS

The valuation includes an estimate of the replacement cost for every structure to be covered. The method used to determine the cost of rebuilding the structures is the current version of the calculation system: CORE LOGIC, INC.

Inspections also include clear photographs of any buildings and ancillary structures the applicant/policyholder wishes to insure.

Where multiple buildings are identical, or nearly so, representative photographs have been used. Photographs of any existing damage are also included.

VALUATION AND BUILDING INFORMATION

Please see attached report under the Property Data section for the following information:

Identity of building inspected

Year of Construction

Total square footage

Number of stories

Number of Units

Construction details

Detailed description of unit use

Overall condition of structure

Common area interior finishes

Type and condition of all ancillary structures on the property, including non-residential Buildings and amenity package

Distance to Tidal water

Detailed description and condition of exposures such as fireplaces, porches, decks, balconies, cooking exposures

Detailed descriptions of other property or liability hazards

I P Risk Services, Inc.







This insurance inspection report is based on the data collected on the inspection date. No consideration has been given to material premiums and additional items needed to conform to building codes, ordinances; or demolition in connection with reconstruction or the removal of destroyed risk items. The **value of the land** and site improvements have **not** been included. No responsibility is assumed for legal matters, questions of survey, opinions of title, soil or sub-soil conditions, engineering or other technical matters. **This report is not a Real Estate Appraisal. Insurance report only.**

The conclusions in this report are estimated under **normal market** conditions and is considered appropriate for proper normal insurance coverage. **Natural disasters** may drastically **increase** the cost of construction and is **not** feasible to properly estimate. This report does **not** take into consideration cost increases due to any type of abnormal weather and/or abnormal other conditions.

This insurance inspection report is not a guarantee or warranty of any kind. We do not assume any liability for damages which may result from this report. We are not responsible for conditions this report fails to disclose. The report is valid for one year. This insurance inspection report should be updated at least once a year.

Neither our employment nor our compensation in connection with this report is in anyway contingent upon the conclusions reached; this report sets forth all the assumptions and limiting conditions affecting the analysis, insurable analysis and conclusions contained herein; I P Risk Services, Inc., makes no warranties or representations regarding the insurance report conclusions found in this report.

The authors of this report shall not be required to give testimony or appear in court or at any administrative proceeding relating to this inspection report. Construction replacement cost value can be provided by a variety of professionals and as such is not within the definition of appraisal practice. This opinion is from the ASB.

The Association, by accepting this insurance report, agrees to release IP from any claims, demands or damages. The Association, in consideration of IP performing the insurance analysis report, hereby agrees to indemnify, defend and hold harmless IP Risk Services, Inc., from and against any and all liability, damages, losses, claims, demands or lawsuits arising out of or relating to this insurance analysis report. Acceptance of and use of this report constitutes acceptance of the above statements.

IPRISKSERVICES@AOL.COM

POWERED BY CORE LOGIC AND UNDERWRITTEN BY LLOYD'S OF LONDON